
Product: Dishwasher	Diverter valve PMS_2019_01	Reference: Service Support
Update: 2019-10-10		Version: 00


From date 17.09.2109 or. Serial number 9383... there is a new diverter valve. New diverter valve isn't backward compatible (until serial 9383...) because of that it is necessary to install also the insert.

Instruction:

1. Disconnect wiring harness and remove the diverter valve from two hooks (one front one back).



2. Install the insert. Insert is possible to install only in one position. Install it in sequence like on photo bellow (a click must be heard).



3. Attach the new diverter valve and do a TOTAL RESET 02.